

Union House, 36 Quay Street, Auckland, NEW ZEALAND Private Bag 92097, Auckland, NEW ZEALAND

Ph: (09) 774-730 Main Fax: (09) 309-1504 Direct Fax: (09) 35M353

14 February 1992

REF: EBM/cp:261

De-Bug Manufacturing Ltd PO Box 38-100 112 Nelson Street WELLINGTON

Attention: Mr L W Forrest - Director

Dear Sir

RE: "UNION ROTORUA" - LIGHT MARINE DIESEL BUNKER FUEL CONTAMINATION

The above vessel was supplied with over 1000 Tonnes of light marine diesel bunker oil, which was subsequently found to be infected with 'Hormoconis Resinae' (Diesel Bug).

The bacteria caused severe problems with blocked fuel filters. Filter life was reduced from 6 to 8 weeks to 17 hours or less.

Treatment of the fuel with the proper biocide kills the bacteria but does not eliminate the dead biomass, which still causes problems with filter blockage. Further, the virtual impossibility of eliminating all water in the bunker fuel tanks, means that re-infection may occur.

On fitting the De-Bug L4000 magnetic devices, it was immediately noticeable that fuel filter life was extended and the frequent filter changes were no longer required. Two L4000 devices were fitted in parallel in the fuel tank outlet pipework 'before the fuel forwarding pumps. These two devices cope with up to 78 tonnes of fuel per 24 hours. The third L4000 is fitted in the fuel supply line to the auxiliary diesels.

Cleaning of the infected bunker tanks may be required, but the De-Bug L4000 devices allow this to be scheduled for a convenient time, allowing the vessel to continue a normal trading pattern.



The devices will remain fitted as part of the ship equipment.

For information, the main propulsion machinery is a single G.E. 5002 gas turbine driving a 20MW alternator at 6.6kv, with shafts being turned by A.C. electric motors.

Auxiliary electrical power is from two 16-cylinder D399 Caterpillar generating sets.

Yours faithfully

Brian McCallin

Superintendent - Technical

Brian Malli.